



TOYOTA Auris: 1HGA794

Vinnnumber:	SB1Z53JE50E097510	Versionname:	AURIS TOUR.SP.HSD Dynamic CVT 99PK Aut.
First Registrationdate:	11/07/2014	Fiscalpower:	
Expertise Mileage:	168632	Power Kw:	73
Bodytype:	Break	Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1715
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/5/16/91 T LightMetal				
Winter tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			1116,03
Alloy rim R R polished, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bodywork, Not original part, Remove lettering			12,50



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), PDR - Paintless dent repair 63,00



Bumper F, Deformed / Strained, Le - Replace and paint 735,00



Tyre repair kit, Missing, E - Replace 210,53

No pictures to display