



## VOLVO XC60: 1TJJ838

Vinnumber:	<b>VV1DZARC1H2133066</b>	Versionname:	<b>D3 Dynamic Edition</b>
First Registrationdate:	<b>17/11/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>138661</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LKW3</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>235/60/18/107 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Uniroyal: 3 mm</b>	Fr.R.	<b>Uniroyal: 3 mm</b>
	Re.L.	<b>Uniroyal: 3 mm</b>	Re.R.	<b>Uniroyal: 3 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	962,92
-------------------	--------

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---------------------------------------------------------	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80




Wing F R, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*

Door R R, Scratch(es), It - Spot repair

115,56



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Door R L, Dent(s) and scratch(es), It - Spot repair

115,56

