



AUDI A6 AVANT: 1LNB519

Vinnumber:	WAUZZZ4GXGN092737	Versionname:	2.0 TDI ULTRA 100KW S TRONIC
First Registrationdate:	26/10/2015	Fiscalpower:	
Expertise Mileage:	156867	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	EX POOL
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	Tow bar fixed
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/92 H LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			607,72
Bumper R, Dent(s), LI - Repair and paint (complete)			302,16



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Dent(s) and scratch(es), Le - Replace and paint

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Stone chip(s), Windscreen repair

0,00



Wing F R, Scratch(es), Acceptable

0,00

