



AUDI A4 AVANT: 1LFF055

Vinnumber:	WAUZZZ8KXFA160863	Versionname:	2.0 TDI ULTRA 100KW
First Registrationdate:	11/09/2015	Fiscalpower:	
Expertise Mileage:	59733	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4102
Maintenance:	28100KM OF 677 DGN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	DVD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1205,62
--------------------------	----------------

Alloy rim F L, Scratch(es), Acceptable	0,00
---	-------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Stone chip(s), Acceptable

0,00



Tailgate, Dent(s), It - Spot repair

115,56



Door F L, Dent(s) and scratch(es), Acceptable

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R, Scratch(es), Acceptable

0,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Door F R, Scratch(es), 67 - Polish

0,00



Bumper grille, Broken, E - Replace

32,40



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Wing R R, Scratch(es), 67 - Polish

0,00



Wing R L, Scratch(es), Acceptable

0,00



Bumper F, Deformed / Strained, Le - Replace and paint

0,00



Door R R, Scratch(es), 67 - Polish

0,00





Door frame F L, Scratch(es), Acceptable

0,00

