



SKODA OCTAVIA COMBI: 1LUT351

Vinnumber:	TMBJG9NE7G0106514	Versionname:	1.6 CRTDI 81KW GREENLINE AMBITION
First Registrationdate:	10/12/2015	Fiscalpower:	
Expertise Mileage:	92777	Power Kw:	81
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4429
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	901,35
-------------------	---------------

Window F L door, Scratch(es), E - Replace	0,00
---	-------------



Roof, Dent(s), PDR - Paintless dent repair 63,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L polished, Scratch(es), I - Repair 0,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Rear spoiler, Dent(s), PDR - Paintless dent repair 0,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Stain, Cleaning 0,00



Ignition key, Missing, E - Replace 0,00



Alloy rim F R polished, Scratch(es), Acceptable 0,00

No pictures to display