



RENAULT Trafic: 1FOR165

Vinnumber:	VF1FLA0AEDY476236	Versionname:	TRAFIC 27 B/F L1H1 Confort FAP(E5)90PK
First Registrationdate:	9/09/2013	Fiscalpower:	
Expertise Mileage:	183414	Power Kw:	66
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	LCV10
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics

Limited Technical Inspection

Tires wear profile	OK	Battery functioning	Yes
Idle position	OK	Power steering	Yes
Engine startingtime	OK	Sound engine	OK
Exhaust gass	OK	Clutch test	OK
Handbrake	OK	Wiper fluid level	OK
		Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/65/16/92 H Steel				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	907,31
-------------------	---------------

Trunk door R R, Dent(s), Acceptable	0,00
-------------------------------------	-------------

No pictures to display

Seat cover F R, Burned, Smart repair	64,32
--------------------------------------	--------------



Trunk door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	250,00
---	---------------



Bumper R, Scratch(es), Smart repair

110,64



Bumper corner R R, Scratch(es), Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

0,00

No pictures to display

Maintenance, Maintenance, Execute

0,00



Door panel F R, Dirty, Cleaning

25,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Bumper corner R L, Scratch(es), Smart repair

110,64



Interior, Damaged, Acceptable

0,00



Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Door R R, Dent(s), Acceptable

0,00

No pictures to display

Rocker panel inner F R, Dent(s), LI - Repair and paint (complete)

115,56



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display