



**RENAULT Kangoo Express: 1FNT730**

Vinnnumber:	<b>VF1FW58H549447971</b>	Versionname:	<b>KANGOO EXPR.MAXI Energy Gr.Conf.90PK</b>
First Registrationdate:	<b>2/09/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>181724</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4409</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Rear parking sensors
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/92 MS Steel</b>			
Winter tyres:	Fr.L.	<b>Other: 6 mm</b>	Fr.R.	<b>Other: 6 mm</b>
	Re.L.	<b>Other: 7 mm</b>	Re.R.	<b>Other: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>2169,35</b>
-------------------	----------------

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	<b>115,56</b>
--	---------------



Wheel cover F R, Scratch(es), E - Replace	<b>22,50</b>
---	--------------



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 22,50



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete) 361,13



Sidewall panel RR, Scratch(es), Forfeit 115,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Dent(s), It - Spot repair 115,56



Internal Boot Lining L, Hole, E - Replace 15,00



Wheel cover F L, Scratch(es), E - Replace 22,50



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Door R R, Scratch(es), LI - Repair and paint (complete) 238,76



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 22,50



Windscreen, Stone chip(s), E - Replace 395,40



Bumper F, Scratch(es), Smart repair 110,64



Door F L, Dent(s), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15

