



**BMW 3 GRAN TURISMO: 1KTP642**

Vinnumber:	<b>WBA3Y11000GD87666</b>	Versionname:	<b>2.0 318D (100KW) GRAN TURISMO</b>
First Registrationdate:	<b>1/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>88870</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Dark Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2303</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	<b>Tow bar fixed</b>
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/55/17/97 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Vredestein: 8 mm</b>	Fr.R.	<b>Vredestein: 8 mm</b>
	Re.L.	<b>Vredestein: 9 mm</b>	Re.R.	<b>Vredestein: 9 mm</b>


**Assistance equipment**

Total cost ex VAT	<b>672,56</b>
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>





Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, P - Check 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F R, Scratch(es), It - Spot repair 115,56



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 58,80

