



**BMW 1: RB7682**

Vinnumber:	<b>WBA1C11010P529347</b>	Versionname:	<b>1 BER HATCH 118d 143PK</b>
First Registrationdate:	<b>14/11/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>141346</b>	Power Kw:	<b>105</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3311</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	<b>Tow bar removable</b>
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/45/17/92 MS LightMetal</b>			
Winter tyres:	Fr.L.	Fr.R.	Michelin: 4 mm
	Re.L.	Re.R.	Michelin: 5 mm

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>No</b>
Total cost ex VAT			<b>744,73</b>
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>





Tyre repair kit, Missing, E - Replace 210,53



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 100,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper grille, Broken, E - Replace 32,40

