



BMW 2 GRAN TOURER: 1LSK047

Vinnumber:	WBA2E510505C92124	Versionname:	2.0 218D (100KW) GRAN TOURER
First Registrationdate:	23/11/2015	Fiscalpower:	
Expertise Mileage:	112088	Power Kw:	100
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4531
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1078,60
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Rear window, Scratch(es), E - Replace

370,00



Alloy rim F R polished, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Bad repair, LI - Repair and paint (complete)

0,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Bad repair, LI - Repair and paint (complete)

0,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Bad repair, LI - Repair and paint (complete)

0,00



Door R R, Bad repair, LI - Repair and paint (complete)

0,00

