


BMW 1 HATCH: 1LGV742

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | WBA1V910505B19545 | Versionname: | 1.5 116D EFFICIENTDYNAMICS EDIT. (85KW) |
| First Registrationdate: | 24/09/2015 | Fiscalpower: | |
| Expertise Mileage: | 67146 | Power Kw: | 85 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 4116 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|----------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Seats F heated | |
| Type of headlighting | Headlighting LED |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining artificial leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
| | 205/55/16/92 MS LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|--------------------------------------|------------|------------|---------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 487,20 |
| Bumper R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Windscreen, Scratch(es), E - Replace | | | 487,20 |

