



BMW 3 TOURING: 1JHE102

Vinnumber:	WBA3K11060F836921	Versionname:	2.0 318D (100KW) TOURING
First Registrationdate:	18/12/2014	Fiscalpower:	
Expertise Mileage:	117582	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4414
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1139,30
-------------------	----------------

Ignition key, Missing, E - Replace	150,00
------------------------------------	---------------

No pictures to display

Foglight R, Broken, E - Replace	138,00
---------------------------------	---------------



Bumper F, Dent(s) and scratch(es), Le - Replace and paint

0,00



Roof pillar L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Scratch(es), LI - Repair and paint (complete)

481,50



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

