



BMW 4 GRAN COUPE: 1JPT709

Vinnumber:	WBA4D51050D424619	Versionname:	2.0 418D (100KW) GRAN COUPE
First Registrationdate:	3/02/2015	Fiscalpower:	
Expertise Mileage:	102495	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3322
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1325,58

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 417,84



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Bumper F R, Scratch(es), It - Spot repair 115,56



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Foglight L, Crack, E - Replace 156,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 0,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Seat cover F L, Damaged, Acceptable 0,00

