



**BMW X5: 1LTD820**

|                                    |                          |              |                                   |
|------------------------------------|--------------------------|--------------|-----------------------------------|
| Vinnumber:                         | <b>WBAKT410600K97424</b> | Versionname: | <b>2.0 SDRIVE25D (155KW) AUTO</b> |
| First Registrationdate:            | <b>27/11/2015</b>        | Fiscalpower: |                                   |
| Expertise Mileage:                 | <b>81511</b>             | Power Kw:    | <b>155</b>                        |
| Bodytype:                          |                          | Body color:  | <b>Black</b>                      |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                    |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                  |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                         |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>3205</b>                       |
| Battery functioning:               | <b>Yes</b>               |              |                                   |
| Number of doors:                   | <b>5</b>                 |              |                                   |
| Number of seats:                   | <b>5</b>                 |              |                                   |
| Number head rests:                 | <b>5</b>                 |              |                                   |
| Rims summer:                       | <b>Aluminium</b>         |              |                                   |
| Category:                          | <b>Passenger Car</b>     |              |                                   |
| Oil level:                         | <b>OK</b>                |              |                                   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                   |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Front parking sensors            |
| Cruise Control                 | Rear parking sensors             |
| Steering wheel multifunctional |                                  |
| Seats F heated                 |                                  |
| Type of headlighting           | <b>Headlighting Xenon</b>        |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                   |       |                       |       |                       |
|-----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>225/55/18/92 MS LightMetal</b> |       |                       |       |                       |
| Winter tyres:                     | Fr.L. | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|                                   | Re.L. | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|  |            |            |             |
|--|------------|------------|-------------|
| Repair kit                             | <b>Yes</b> | Compressor | <b>Yes</b>  |
| Total cost ex VAT                      |            |            | <b>0,00</b> |
| Alloy rim R L, Scratch(es), Acceptable |            |            | <b>0,00</b> |
| <i>No pictures to display</i>          |            |            |             |
| Alloy rim R R, Scratch(es), Acceptable |            |            | <b>0,00</b> |
| <i>No pictures to display</i>          |            |            |             |