


**BMW X4: 1RSP420**

Vinnumber:	<b>WBAXX110100T41242</b>	Versionname:	<b>2.0 XDRIVE20D (140KW) 4WD</b>
First Registrationdate:	<b>20/02/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>109672</b>	Power Kw:	<b>140</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3227</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	<b>HD</b>	Sun Roof electric	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	<b>Tow bar removable</b>
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Head-up Display			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>245/50/18/100 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Yokohama: 3 mm</b>	Fr.R.	<b>Yokohama: 3 mm</b>
	Re.L.	<b>Yokohama: 3 mm</b>	Re.R.	<b>Yokohama: 3 mm</b>

**Assistance equipment**

Total cost ex VAT	210,56
Bumper F R, Scratch(es), It - Spot repair	115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

