



BMW 3 TOURING: 1LFF068

Vinnumber:	WBA8H71000K397987	Versionname:	2.0 318D (100KW) TOURING
First Registrationdate:	11/09/2015	Fiscalpower:	
Expertise Mileage:	86162	Power Kw:	100
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	PARKING KT
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 3 mm	Re.R.	Hankook: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			621,20
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Deformed / Strained, Le - Replace and paint 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Protection plate M, Hole, E - Replace 124,40

