



FORD Transit 350M: 1FSI373

Vinnumber:	WF0XXXTFXDG46764	Versionname:	TRANS.350M B/F MWB RWD Amb.DPF(EU5)100PK
First Registrationdate:	9/10/2013	Fiscalpower:	
Expertise Mileage:	208894	Power Kw:	74
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV21
Number of doors:	4		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/75/16/114 R Steel				
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 487,62

Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Chemical polution, Acceptable 0,00

No pictures to display

Sill outer L, Scratch(es), Acceptable 0,00

No pictures to display

Backpack, Not original part, Acceptable 0,00

Bodywork, not original part, Acceptable 0,00

No pictures to display

Seat cover F L, Worn, Acceptable 0,00



Wheel cover F L, Missing, E - Replace 22,50



Rearview mirror housing L, Broken, E - Replace 84,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R R, Scratch(es), It - Spot repair 115,56



Sill outer R, Dent(s), It - Spot repair 115,56

