



BMW 5: 1FLF410

Vinnumber:	WBAMX11040DY19147	Versionname:	5 TOURING 520da Start/Stop 163PK aut
First Registrationdate:	5/08/2013	Fiscalpower:	
Expertise Mileage:	141177	Power Kw:	120
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2119
Maintenance:	BINNEN 8000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	3377,12
-------------------	----------------

Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

302,16



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Wing F R, Chemical pollution, LI - Repair and paint (complete)

264,21



Bonnet, Chemical pollution, LI - Repair and paint (complete)

348,09



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00




Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

417,84



Windscreen, Repaired, E - Replace

560,64



Luggage space cover, Damaged, E - Replace 288,00



Rearlight L, Broken, E - Replace 132,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 302,16



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

