



CITROEN C4 Picasso: 1GAA477

Vinnumber:	VF73A9HC8DJ836508	Versionname:	GR.C4 PICASSO Intensive ETG 115PK Aut.
First Registrationdate:	3/12/2013	Fiscalpower:	
Expertise Mileage:	115301	Power Kw:	85
Bodytype:		Body color:	Red
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2211
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Rear parking sensors	
Radio multimedia	Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 MS LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1456,88
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80





Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Wing R L, Repaired, Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer R, Dent(s), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), Acceptable

0,00

No pictures to display

Maintenance, Maintenance, Execute

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Ignition key, Missing, E - Replace

150,00

No pictures to display