



BMW 3: 1HSG048

Vinnumber:	WBA8J31040F698168	Versionname:	3 TOURING 318dX 143PK
First Registrationdate:	19/09/2014	Fiscalpower:	
Expertise Mileage:	66398	Power Kw:	105
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	PARKING VOOR
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	NOT OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 W Steel			
Summer tyres:	Fr.L.	Fr.R.	Michelin: 4 mm
	Re.L.	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	0,00
-------------------	------

Wing R R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

No pictures to display

Door R R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display