



MERCEDES A: 1NSD756

Vinnumber:	WDD1760121V145854	Versionname:	1.5 A 180 D BLUEEFFICIENCY STYLE EDITION
First Registrationdate:	14/04/2016	Fiscalpower:	
Expertise Mileage:	68912	Power Kw:	80
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3229
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	434,32
--------------------------	---------------

Bonnet, Chemical polution, 67 - Polish	0,00
--	-------------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------


No pictures to display

Roof, Chemical polution, 67 - Polish	0,00
--------------------------------------	-------------

No pictures to display

Rear window, Scratch(es), E - Replace

370,00



Wing R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Repaired, Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Rear spoiler, Scratch(es), 67 - Polish

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Floor covering F L, Hole, Smart repair

64,32

