



MERCEDES A: 1PST013

Vinnumber:	WDD1760121J518049	Versionname:	A 180 d BlueEFFICIENCY Edition
First Registrationdate:	8/09/2016	Fiscalpower:	
Expertise Mileage:	93735	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	PARKING KT
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1135,71
Wheel cover F L, Scratch(es), E - Replace	30,00



Wheel cover F R, Scratch(es), E - Replace 30,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display


Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 30,00



Rear window, Scratch(es), E - Replace 370,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Rear spoiler, Chemical polution, LI - Repair and paint (complete) 115,56



Roof, Chemical polution, 67 - Polish 0,00

No pictures to display