



**MERCEDES CLA SHOOTING BRAKE: 1TAE813**

|                                    |                          |              |                  |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber:                         | <b>WDD1179121N577972</b> | Versionname: | <b>CLA 180 d</b> |
| First Registrationdate:            | <b>4/09/2017</b>         | Fiscalpower: |                  |
| Expertise Mileage:                 | <b>137290</b>            | Power Kw:    | <b>80</b>        |
| Bodytype:                          |                          | Body color:  | <b>Blue</b>      |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>   |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b> |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>        |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>3618</b>      |
| Battery functioning:               | <b>Yes</b>               |              |                  |
| Number of doors:                   | <b>5</b>                 |              |                  |
| Number of seats:                   | <b>5</b>                 |              |                  |
| Number head rests:                 | <b>5</b>                 |              |                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                  |
| Category:                          | <b>Passenger Car</b>     |              |                  |
| Oil level:                         | <b>OK</b>                |              |                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                  |

**Options**

|                                |                                  |                       |
|--------------------------------|----------------------------------|-----------------------|
| Radio CD                       |                                  | Central consol F      |
| GPS storage                    |                                  | Luggage cover         |
| GPS storage                    | <b>SD</b>                        | Front parking sensors |
| Windows electric F             |                                  | Rear parking sensors  |
| Windows electric R             |                                  |                       |
| Cruise Control                 |                                  |                       |
| Steering wheel multifunctional |                                  |                       |
| Type of headlighting           | <b>Headlighting Halogen</b>      |                       |
| Type of GPS                    | <b>GPS big screen color</b>      |                       |
| Type of Lining                 | <b>Lining artificial leather</b> |                       |
| Type of climate control        | <b>Manual climate control</b>    |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>225/40/18/92 V LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|                                  | Re.L. | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>215,00</b> |
|-------------------|---------------|

|                                     |             |
|-------------------------------------|-------------|
| Seat cover F L, Damaged, Acceptable | <b>0,00</b> |
|-------------------------------------|-------------|



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Compressor, Incomplete, E - Replace 25,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

