



**MERCEDES B: 1TKZ745**

Vinnumber:	<b>WDD2462121J394521</b>	Versionname:	<b>1.5 B 180 D STYLE</b>
First Registrationdate:	<b>19/04/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>137165</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3109</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>SD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting LED</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/92 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 5 mm</b>	Fr.R.	<b>Goodyear: 5 mm</b>
	Re.L.	<b>Goodyear: 6 mm</b>	Re.R.	<b>Goodyear: 6 mm</b>

**Assistance equipment**

Total cost ex VAT	<b>519,80</b>
Rear window, Scratch(es), E - Replace	<b>0,00</b>



Wing R L, Dent(s), PDR - Paintless dent repair

63,00



Door R R, Dent(s), Acceptable

0,00

*No pictures to display*


Alloy rim F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bonnet, Chemical polution, 67 - Polish

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Ignition key, Missing, E - Replace

150,00

*No pictures to display*

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80

