


**MERCEDES A: 1PRU482**

Vinnumber:	<b>WDD1760121J511369</b>	Versionname:	<b>A 180 d BlueEFFICIENCY Edition</b>
First Registrationdate:	<b>1/09/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>62295</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2722</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Type of Tow bar	<b>Tow bar removable</b>
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/95 V Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	612,30
-------------------	--------























Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bonnet, Chemical pollution, 67 - Polish	0,00
---	------

*No pictures to display*

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>		
Wheel cover F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Rear window, Scratch(es), Acceptable		0,00
		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Scratch(es), LI - Repair and paint (complete)		211,80
		
		
		
Wheel cover R R, Scratch(es), E - Replace		30,00
		
Wheel cover R L, Scratch(es), E - Replace		30,00
		
		
Sill outer R, Scratch(es), LI - Repair and paint (complete)		310,50
		
		
Wheel cover F R, Scratch(es), E - Replace		30,00

