



MERCEDES E BREAK: 1LCF711

Vinnumber:	WDD2122061B243662	Versionname:	2.1 E 200 BLUETEC ELEGANCE
First Registrationdate:	18/08/2015	Fiscalpower:	
Expertise Mileage:	104394	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	1323
Maintenance:	MELDING		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/45/17/92 MS LightMetal				
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Total cost ex VAT	1277,20
Alloy rim R L, Scratch(es), E - Replace	277,44



Roof, Chemical pollution, 67 - Polish 0,00

No pictures to display Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display Rear window, Not original part, Remove lettering 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 278,16



Side window R L, Not original part, Remove lettering 0,00



Door F R, Dent(s), Acceptable 0,00

No pictures to display Maintenance, Maintenance, Execute 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F L, Scratch(es), E - Replace 277,44





Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

