



MERCEDES A180: 1PUY032

Vinnumber:	WDD1760121J529338	Versionname:	A 180 d BlueEFFICIENCY Edition
First Registrationdate:	26/09/2016	Fiscalpower:	
Expertise Mileage:	75951	Power Kw:	80
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	ASS 83 PLUS 157 D	Parking lot	PARKING GARAGE
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Type of Tow bar
Windows electric F	No Tow bar
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 V Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	490,00
Wheel cover F R, Scratch(es), E - Replace	30,00



Tailgate, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Roof pillar R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror basis L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), E - Replace	30,00



Wheel cover F L, Scratch(es), E - Replace	30,00
---	-------



Door F R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), E - Replace	370,00



Wheel cover R L, Scratch(es), E - Replace	30,00
---	-------



Door R R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Repaired, Acceptable	0,00
<i>No pictures to display</i>	