


**OPEL MOVANO: GL9121**

Vinnumber:	<b>WOLMRFCSCGB089149</b>	Versionname:	<b>2.3CDTI 92KW MWB HRF 3.3T</b>
First Registrationdate:	<b>9/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>85521</b>	Power Kw:	<b>92</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV18</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/65/16/107 R Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	2135,51
Sill outer R, Scratch(es), LI - Repair and paint (complete)	232,88



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

375,15



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Interior, Dirty, Acceptable

0,00

No pictures to display

Wheel cover F L, Missing, E - Replace

22,50



Boot carpet, Damaged, E - Replace

171,00



Seat cover F L, Damaged, E - Replace

300,00



Trunk door R L, Dent(s) and scratch(es), It - Spot repair

115,56



Aerial, Damaged, E - Replace

11,25



Ignition key, Missing, E - Replace

150,00

No pictures to display

Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete)

526,02



Wing R L, Scratch(es), LI - Repair and paint (complete)

231,15

