



**MERCEDES C COUPE: ZM8146**

Vinnumber:	<b>WDD2053401F647442</b>	Versionname:	<b>C 180</b>
First Registrationdate:	<b>29/09/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>41358</b>	Power Kw:	<b>115</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4633</b>
Maintenance:	<b>B1 DANS 62 JOURS</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>2</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>SD</b>	Seats electric F L	
GPS storage		Seats electric F R	
Windows electric F		Central consol F	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Alarm		Type of Tow bar	<b>No Tow bar</b>
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Level control			
Sport seats			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**


<b>225/45/18/95 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Continental: 3 mm</b>	Re.R.	<b>Continental: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>787,60</b>
-------------------	---------------

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
---	--------------



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), LI - Repair and paint (complete) 356,20



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Tyre F R, Tear, E - Replace 132,00



Outer door handle F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding F M, Scratch(es), E - Replace 14,40



Alloy rim F R polished, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Instrument panel cover, Not original part, P - Check	0,00
--	------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*