



NISSAN X-TRAIL: 1LFT585

Vinnumber:	JN1JCAT32U0012447	Versionname:	1.6 DCI CONNECT EDITION
First Registrationdate:	16/09/2015	Fiscalpower:	
Expertise Mileage:	134750	Power Kw:	96
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4612
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Type of headlighting	Rear parking sensors
Type of GPS	Type of Tow bar
Type of Lining	
Type of climate control	

Headlighting Halogen
GPS big screen color
Lining fabrics
Autom climate control

Tow bar removable

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/19/99 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Total cost ex VAT	930,78
Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	264,21



Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar L, Dent(s), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R polished, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F L, Hole, Smart repair

64,32



Alloy rim R R polished, Rust, Acceptable

0,00

No pictures to display

Maintenance book, Missing, E - Replace

0,00

No pictures to display

Alloy rim R L polished, Rust, Acceptable

0,00

No pictures to display

Wing F L, Dent(s), Acceptable

0,00

No pictures to display