


RENAULT CLIO: 1LTB082

Vinnumber:	VF15R0J0A54168213	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	27/11/2015	Fiscalpower:	
Expertise Mileage:	98553	Power Kw:	66
Bodytype:		Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1110
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 MS Steel			
Summer tyres:	Fr.L.	Michelin: 0 mm	Fr.R.	Michelin: 0 mm
	Re.L.	Michelin: 0 mm	Re.R.	Michelin: 0 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1520,94

Wheel cover R L, Broken, E - Replace 24,00



Wheel cover F R, Missing, E - Replace

24,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 24,00



Door F L, Dent(s) and scratch(es), It - Spot repair 115,56



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 246,56



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Rear window, Scratch(es), E - Replace 320,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 176,14



Bonnet, Bad repair, LI - Repair and paint (complete) 0,00



Wheel cover F L, Scratch(es), E - Replace 24,00



Windscreen, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Burned, E - Replace 312,00

