


**VOLKSWAGEN TOURAN: 1LVA910**

|                                    |                          |              |                |
|------------------------------------|--------------------------|--------------|----------------|
| Vinnumber:                         | <b>WVGZZZ1TZGW532007</b> | Versionname: |                |
| First Registrationdate:            | <b>14/12/2015</b>        | Fiscalpower: |                |
| Expertise Mileage:                 | <b>120154</b>            | Power Kw:    | <b>81</b>      |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>    |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b> |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>   |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>      |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3412</b>    |
| Number of doors:                   | <b>5</b>                 |              |                |
| Number of seats:                   | <b>7</b>                 |              |                |
| Number head rests:                 | <b>7</b>                 |              |                |
| Rims summer:                       | <b>Steel</b>             |              |                |
| Category:                          | <b>Passenger Car</b>     |              |                |
| Oil level:                         | <b>OK</b>                |              |                |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Central consol F      |                   |
| GPS storage                    | <b>SD</b>                    | Luggage cover         |                   |
| GPS storage                    |                              | Front parking sensors |                   |
| Windows electric F             |                              | Rear parking sensors  |                   |
| Windows electric R             |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Cruise Control                 |                              |                       |                   |
| Steering wheel multifunctional |                              |                       |                   |
| Seats F heated                 |                              |                       |                   |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                       |       |                       |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
|               | <b>205/60/16/96 H Steel</b> |                       |       |                       |
| Winter tyres: | Fr.L.                       | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|               | Re.L.                       | <b>Uniroyal: 6 mm</b> | Re.R. | <b>Uniroyal: 6 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 423,60 |
|-------------------|--------|

|   |      |
|---|------|
| Roof pillar L, Chemical polution, 67 - Polish | 0,00 |
|---|------|

*No pictures to display*

|  |      |
|--|------|
| Wheel cover R R, Scratch(es), Acceptable | 0,00 |
|--|------|

|   |  |        |
|---|--|--------|
| <i>No pictures to display</i>                                       |  |        |
| Wing R R, Dent(s), Acceptable                                       |  | 0,00   |
| <i>No pictures to display</i>                                       |  |        |
| Door F R, Scratch(es), Acceptable                                   |  | 0,00   |
| <i>No pictures to display</i>                                       |  |        |
| Rearview mirror housing R, Scratch(es), Acceptable                  |  | 0,00   |
| <i>No pictures to display</i>                                       |  |        |
| Bumper R, Scratch(es), LI - Repair and paint (complete)             |  | 211,80 |
|   |  |        |
| Tailgate, Dent(s), Acceptable                                       |  | 0,00   |
| <i>No pictures to display</i>                                       |  |        |
| Door F L, Scratch(es), Acceptable                                   |  | 0,00   |
| <i>No pictures to display</i>                                       |  |        |
| Door R L, Scratch(es), Acceptable                                   |  | 0,00   |
| <i>No pictures to display</i>                                       |  |        |
| Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) |  | 211,80 |
|   |  |        |
| Wheel cover F R, Scratch(es), Acceptable                            |  | 0,00   |
| <i>No pictures to display</i>                                       |  |        |