



VOLKSWAGEN GOLF VII: 1LLZ322

Vinnumber:	WVWZZZAUZGP051362	Versionname:	1.6 TDI 81KW TRENDLINE
First Registrationdate:	23/10/2015	Fiscalpower:	
Expertise Mileage:	123749	Power Kw:	81
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LKW2
Maintenance:	22.500 KM OU 215 JOURS		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Continental: 8 mm	Fr.R.	Continental: 8 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 1031,55

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Cleaning 25,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), LI - Repair and paint (complete) 414,35



Seat cover R R, Stain, Cleaning 25,00



Wing R R, Dent(s), LI - Repair and paint (complete) 452,20



Mirror side blinker R, Broken, E - Replace 30,00



Wheel cover F R, Scratch(es), E - Replace 30,00



Seat cover F L, Stain, Cleaning 25,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00

