



VOLKSWAGEN PASSAT VARIANT: 1LSV668

Vinnumber:	WVWZZZ3CZGE127218	Versionname:	2.0 TDI MSQ VARIANT HIGHLINE
First Registrationdate:	25/11/2015	Fiscalpower:	
Expertise Mileage:	134007	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	A12
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather and alcantara
Type of climate control	Autom climate control
Adaptive cruise control	Tow bar removable

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/17/98 W LightMetal				
Summer tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 3 mm	Re.R.	Vredestein: 3 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			0,00
Wing R L, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror housing R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Broken, Le - Replace and paint			0,00



Windscreen trim, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing F L, Bad repair, LI - Repair and paint (complete)	0,00
--	------



Door R R, Scratch(es), LI - Repair and paint (complete)	0,00
---	------

