



**VOLKSWAGEN Passat: 1GTA519**

Vinnumber:	<b>WVWZZZ3CZEE130546</b>	Versionname:	<b>PASSAT VAR Comfortline 136PK</b>
First Registrationdate:	<b>22/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>195159</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2429</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/55/16/97 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Other: 5 mm</b>	Fr.R.	<b>Other: 5 mm</b>
	Re.L.	<b>Other: 5 mm</b>	Re.R.	<b>Other: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	2368,54
Rearview mirror glass R, Broken, E - Replace	18,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Tyre R R, Flat, E - Replace

132,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Rust, LI - Repair and paint (complete)

318,35



Bonnet, Bad repair, LI - Repair and paint (complete)

290,08



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Rust, Acceptable

0,00



Wing F R, Dent(s), Acceptable 0,00

*No pictures to display*

Door R L, Rust, LI - Repair and paint (complete) 318,35



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Wing R R, Deformed / Strained, LI - Repair and paint (complete) 308,20



Tailgate, Dent(s), PDR - Paintless dent repair 63,00



Bonnet, Not original part, Acceptable 0,00



Outer door handle R R, Scratch(es), LI - Repair and paint (complete) 115,56

