



VOLKSWAGEN Touran: 1HRT825

Vinnnumber:	WVGZZZ1TZEW097065	Versionname:	TOURAN Highline BMT St&St 7pl.105PK
First Registrationdate:	16/09/2014	Fiscalpower:	
Expertise Mileage:	91313	Power Kw:	77
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	PARKING GARAGE
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/92 MS LightMetal				
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Total cost ex VAT	2306,67
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F M, Scratch(es), Smart repair 110,64



Wing R R, Dent(s), LI - Repair and paint (complete) 308,20



Gear shift lever cover, Worn, Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Door F L, Bad repair, Acceptable 0,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00




Wing R L, Bad repair, Acceptable 0,00



Bonnet, Scratch(es), LI - Repair and paint (complete) 25,00



Bumper R, Dent(s) and scratch(es), Le - Replace and paint 651,00



Wing F R, Bad repair, Acceptable 0,00



Maintenance, Maintenance, Execute 0,00

No pictures to display

Door R L, Bad repair, Acceptable 0,00

