



VOLVO XC60: 1LEH281

Vinnumber:	VV1DZARC1G2827068	Versionname:	2.0 D3 2WD KINETIC
First Registrationdate:	4/09/2015	Fiscalpower:	
Expertise Mileage:	119676	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1413
Maintenance:	IN 29380 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/108 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	613,16
Floor covering F L, Hole, E - Replace	264,00



Wing R R, Chemical polution, 67 - Polish

0,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Door panel R R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Chemical polution, 67 - Polish

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Door panel R L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display