


**VOLKSWAGEN PASSAT VARIANT: 1GHP121**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber:                         | <b>VVWZZZ3CZEE042715</b> | Versionname: | <b>1.6 CR TDI 77KW BMT COMFORTLINE</b> |
| First Registrationdate:            | <b>10/02/2014</b>        | Fiscalpower: |  |
| Expertise Mileage:                 | <b>150872</b>            | Power Kw:    | <b>77</b>                              |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                            |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                         |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                       |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                              |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3729</b>                            |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>5</b>                 |              |  |
| Number head rests:                 | <b>5</b>                 |              |  |
| Rims summer:                       | <b>Aluminium</b>         |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional | Type of Tow bar              |
| Radio multimedia               | <b>No Tow bar</b>            |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                         |       |                         |
|---------------|----------------------------------|-------------------------|-------|-------------------------|
|               | <b>215/55/16/97 H LightMetal</b> |                         |       |                         |
| Winter tyres: | Fr.L.                            | <b>Vredestein: 5 mm</b> | Fr.R. | <b>Vredestein: 5 mm</b> |
|               | Re.L.                            | <b>Vredestein: 5 mm</b> | Re.R. | <b>Vredestein: 5 mm</b> |

**Assistance equipment**

|  |            |      |            |
|--|------------|------|------------|
| Spare wheel                              | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|   |      |
|---|------|
| Total cost ex VAT                             | 0,00 |
| Door R L, Dent(s) and scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>                 |      |
| Alloy rim F L, Scratch(es), Acceptable        | 0,00 |
| <i>No pictures to display</i>                 |      |
| Door R R, Dent(s), Acceptable                 | 0,00 |
| <i>No pictures to display</i>                 |      |

No pictures to display

|                                       |      |
|---------------------------------------|------|
| Bonnet, Chemical polution, Acceptable | 0,00 |
|---------------------------------------|------|

No pictures to display

|  |      |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

|   |      |
|---|------|
| Bumper R, Dent(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display