



## VOLKSWAGEN Touran: 1GUH736

Vinnnummer:	<b>WVGZZZ1TZEWO90906</b>	Versionname:	<b>TOURAN Highline BMT St&amp;St 7pl.105PK</b>
First Registrationdate:	<b>2/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>152163</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1427</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Sun Roof electric	
GPS storage	<b>HD</b>	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>


## Degree of wear

<b>205/55/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	1516,15
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35



Ignition key, Broken, E - Replace 150,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s), PDR - Paintless dent repair 63,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80







Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Dent(s), PDR - Paintless dent repair 63,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Rear window, Scratch(es), Acceptable 0,00



Roof, Chemical polution, 67 - Polish 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display