



**VOLVO V60: 1JJR461**

Vinnumber:	<b>VV1FW8481F1250574</b>	Versionname:	<b>1.6 D2 KINETIC</b>
First Registrationdate:	<b>6/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>107307</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color:	<b>GRIS</b>
Transmission:	<b>Front</b>	Paint type:	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer:	<b>Aluminium</b>
Maintenance:	<b>OK</b>	Oil level:	<b>OK</b>
Maintenance:	<b>14567 KM</b>	Parking lot:	<b>X</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>BF Goodrich: 5 mm</b>	Fr.R.	<b>BF Goodrich: 5 mm</b>
	Re.L.	<b>Vredestein: 7 mm</b>	Re.R.	<b>Vredestein: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1507,20</b>
--------------------------	----------------

<b>Alloy rim F L, Scratch(es), LI - Repair and paint (complete)</b>	<b>95,00</b>
---------------------------------------------------------------------	--------------



Sill trim R, Scratch(es), It - Spot repair 115,56



Seat cover R, Dirty, Cleaning 50,00



Seat cover F L, Stain, Cleaning 25,00



Door F R, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), 67 - Polish 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Door F R, Scratch(es), 67 - Polish 0,00

No pictures to display

Wing R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Door F L, Scratch(es), It - Spot repair 115,56



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Seat cover F R, Stain, Cleaning 25,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Rearlight R , Crack, E - Replace 114,00



Door F R, Scratch(es), 67 - Polish 0,00

No pictures to display

Bumper grille F R, Missing, E - Replace 32,40



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Scratch(es), 67 - Polish 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Dent(s), PDR - Paintless dent repair 63,00

