



OPEL Insignia: 1CMG576

Vinnumber:	W0LGT8ELXC1044317	Versionname:	INSIGNIA BRE ecofl.Cosmo S/S DPF 130PK
First Registrationdate:	3/01/2012	Fiscalpower:	
Expertise Mileage:	155007	Power Kw:	96
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3502
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/92 MS LightMetal			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	636,00
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Headlight R, Waterinfiltration, Acceptable	0,00



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Broken, E - Replace 150,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Floor covering F L, Tear, E - Replace 252,00



Inner seat cover L, Crack, E - Replace 44,00



Bonnet, Not original part, Acceptable 0,00



Roof, Not original part, Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

