



VOLKSWAGEN TRANSPORTER: 1LUY383

Vinnumber:	WV1ZZZ7HZGH036264	Versionname:	2.0CRTDI 103KW MSQ 2.8T LWB
First Registrationdate:	11/12/2015	Fiscalpower:	
Expertise Mileage:	63015	Power Kw:	103
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3222
Battery functioning:	Yes		
Number of doors:	6		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Aluminium		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/65/16/92 H LightMetal				
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			440,00
Trunk door R L, Dent(s), LI - Repair and paint (complete)			220,00



Wing R L, Scratch(es), Acceptable		0,00
-----------------------------------	--	-------------

No pictures to display

Door R L, Scratch(es), Acceptable		0,00
-----------------------------------	--	-------------

<i>No pictures to display</i>		0,00
Trunk door R R, Dent(s), LI - Repair and paint (complete)		220,00
		
Maintenance, Maintenance, Execute		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		