


**BMW 1 HATCH: 1LFX510**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber:                         | <b>WBA1V910705B19420</b> | Versionname: | <b>1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)</b> |
| First Registrationdate:            | <b>17/09/2015</b>        | Fiscalpower: | <b>85</b>                                      |
| Expertise Mileage:                 | <b>111859</b>            | Power Kw:    | <b>85</b>                                      |
| Bodytype:                          |                          | Body color:  | <b>Dark Brown</b>                              |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                                 |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                               |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                      |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2415</b>                                    |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>5</b>                 |              |  |
| Number head rests:                 | <b>5</b>                 |              |  |
| Rims summer:                       | <b>Aluminium</b>         |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Rear parking sensors             |
| Cruise Control                 | Type of Tow bar                  |
| Steering wheel multifunctional | <b>No Tow bar</b>                |
| Seats F heated                 |                                  |
| Radio multimedia               |                                  |
| Type of headlighting           | <b>Headlighting LED</b>          |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>205/55/16/91 H LightMetal</b> |       |                          |       |                          |
| Winter tyres:                    | Fr.L. | <b>Continental: 5 mm</b> | Fr.R. | <b>Continental: 5 mm</b> |
|                                  | Re.L. | <b>Continental: 5 mm</b> | Re.R. | <b>Continental: 5 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

Total cost ex VAT 907,38

Roof, Chemical polution, Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Sill outer R, Scratch(es), LI - Repair and paint (complete) 310,50



Door R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Door R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80

