


BMW 2 Active Tourer: 1JLJ022

Vinnumber:	WBA2B31050V378866	Versionname:	2 ACTIVE TOURER 216d 116PK
First Registrationdate:	16/01/2015	Fiscalpower:	
Expertise Mileage:	82275	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2813
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 MS LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			190,00
Seat cover F L, Damaged, Acceptable			0,00



Door R R, Bad repair, LI - Repair and paint (complete)

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Bad repair, LI - Repair and paint (complete)

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

