



BMW 1 HATCH: 1LKZ182

Vinnumber:	WBA1V910905B19936	Versionname:	1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	15/10/2015	Fiscalpower:	
Expertise Mileage:	112485	Power Kw:	85
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4513
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/92 H LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			731,20
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)			95,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Foglight L, Broken, E - Replace 138,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display


Bumper R, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), E - Replace 0,00



Windscreen, Scratch(es), E - Replace 0,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00

