



BMW 3: 1HJR994

| | | | |
|------------------------------------|--------------------------|--------------|----------------------------------|
| Vinnumber: | WBA3Y11050D450520 | Versionname: | 3 GRAN TURISMO 318d 136PK |
| First Registrationdate: | 4/08/2014 | Fiscalpower: | |
| Expertise Mileage: | 163149 | Power Kw: | 100 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metallic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3809 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|----------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining artificial leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-------------------------|-------|-------------------------|
| | 225/55/17/92 MS LightMetal | | | |
| Winter tyres: | Fr.L. | Vredestein: 4 mm | Fr.R. | Vredestein: 4 mm |
| | Re.L. | Vredestein: 5 mm | Re.R. | Vredestein: 5 mm |

Assistance equipment

| | |
|-------------------------------------|--------|
| Total cost ex VAT | 639,00 |
| Seat cover F L, Damaged, Acceptable | 0,00 |



| | |
|-----------------------------|------|
| Bonnet, Dent(s), Acceptable | 0,00 |
|-----------------------------|------|

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Dent(s), LI - Repair and paint (complete) 235,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace 0,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20

