



BMW 318 D: 1HZR643

Vinnumber:	WBA3Y11030D900908	Versionname:	GRAN TURISMO 318da 136PK Aut.
First Registrationdate:	7/11/2014	Fiscalpower:	
Expertise Mileage:	182591	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 17000 KM	Parking lot:	2329
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	354,80
-------------------	---------------


Door F L, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	259,80
---	---------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display