



BMW 3 TOURING: 1KEP690

Vinnumber:	WBA3K11030F838691	Versionname:	2.0 318D (100KW) TOURING
First Registrationdate:	15/04/2015	Fiscalpower:	
Expertise Mileage:	152869	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3824
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	1095,70
-------------------	----------------

Seat cover F L, Stain, Cleaning	0,00
---------------------------------	-------------



Roof, Chemical polution, LI - Repair and paint (complete)

481,50




Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Windscreen, Scratch(es), E - Replace

0,00



Rear window, Scratch(es), E - Replace

0,00



Backrest cover F L, Scratch(es), Smart repair

64,32



Bumper R, Dent(s), LI - Repair and paint (complete)

259,80

