



MERCEDES C COUP?: ZM8109

| | | | |
|-------------------------|--------------------------|--------------|------------------|
| Vinnumber: | WDD2053401F648871 | Versionname: | C 180 |
| First Registrationdate: | 5/10/2017 | Fiscalpower: | |
| Expertise Mileage: | 44964 | Power Kw: | 115 |
| Bodytype: | | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Petrol | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2409 |
| Number of doors: | 2 | | |
| Number of seats: | 4 | | |
| Number head rests: | 4 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | SD | Front parking sensors | |
| GPS storage | | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting LED | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 225/45/18/95 Y LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 5 mm | Fr.R. | Continental: 5 mm |
| | Re.L. | Continental: 3 mm | Re.R. | Continental: 3 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--|---------------|
| Total cost ex VAT | 984,80 |
| Wing F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F R, Dent(s) and scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display