


OPEL Corsa: 1JGK232

Vinnumber:	W0L0SDL68E4339510	Versionname:	CORSA BER ecoFLEX Ultimate Edition 95PK
First Registrationdate:	11/12/2014	Fiscalpower:	
Expertise Mileage:	138523	Power Kw:	70
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3212
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Type of Tow bar	No Tow bar
GPS storage	HD		
GPS storage			
Windows electric F			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	185/65/15/88 T LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1433,07
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door frame R R, Scratch(es), Acceptable 0,00

No pictures to display

Foglight R, Scratch(es), Acceptable 0,00

No pictures to display

Internal Boot Lining R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 0,00



Luggage space cover, Missing, E - Replace 192,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Outer door handle F R, Scratch(es), LI - Repair and paint (complete) 115,56



Door seal R, Broken, E - Replace 105,15



Tailgate, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Outer door handle F L, Scratch(es), Acceptable 0,00

No pictures to display

Handbrake cover, Worn, Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Bumper moulding R L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Door F L, Scratch(es), LI - Repair and paint (complete) 254,68



Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display